Sewershed: Dundalk	Consultant: RJN Group, Inc.	Date: YYYYMMDD
Test to be performed:	Ground Condition:	2008/11/03
Smoke Dye	Dry Damp Wet	Supervisor initials:
anhole ID: <u>\$69A1~ 00 MH</u>	21011 111	Notifications - made daily: (Residents, Fire, 311)
	numbers, blower placement location, sans, defect locations and photograph num	
NA Pic # 1329-1402		oil
		Depressed Grass area 10 min 20 sal Drainage area 150 sq ft Manhole leaking at wells 7 Sia Al
		1022
To like the	Van Denga st	
k		
*		
		rjn group

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page <u>1</u> of <u>2</u>
Sewershed: Dundalk	Consultant: RJN Group, Inc.	Date: YYYYMMDD Zoo 8 / 11 / 0 3
Test to be performed: Smoke Dye <u>✓</u>	Ground Condition: Dry <u>✓</u> Damp Wet	Supervisor initials:
Manhole ID: <u>569A1_ 001 MH</u>	Test ID: D1047 - 191	Notifications - made daily: <u>√</u> (Residents, Fire, 311)

Field Sketch: Show all manholes with numbers, blower placement location, sandbag or isolation device location, street names, building addresses and locations, defect locations and photograph numbers.





D1047-191-OB01-P01

D1047-191-OB01-P02



D1047-191-OB01-P03



D1047-191-OB01-P04

rjngroup